

S-E-C-R-E-T

25X1

-2-

Three lightning conductors, each about 30 to 40 cm in length, have been fitted on the apex of the roof of each of the three sheds. A triple-wire overhead electrical power system has been laid between this depot and the transformer located on the western side of the airfield fuel installation. An entire lighting system has been set up about three meters inside the entire barbed-wire perimeter fence surrounding this depot and connected to the overhead power grid from the airfield. There are no electrical or other fittings in any of the three storage sheds, each of which is completely bare and without any lighting whatsoever. Two hand operated water pumps have been constructed on the site.

25X1

A wooden watch tower has been built in each of the four corners of the 2.5 meter-high barbed-wire perimeter fence.

Along the outside of this entire fence a strip, in width, has been cleared and levelled.

A concrete road, about five meters in width and 15 to 20 cm in thickness has been laid to connect this munition depot to the northeast corner of the airfield. As of 23 April, this entire depot was empty and completely unguarded.

4. Power Supply:

- a. There is no main generator on the airfield, the electric power being supplied by an overhead grid system consisting of four heavy wires which connect the brick-built transformer joining the fuel installation to a similar transformer located on the southeastern side of the village of Tutow, from where it joins the local overhead high-tension grid. A stand-by generator has been built in the northeast corner of the airfield.
- b. From the airfield transformer two overhead power lines lead as follows:
 1. To the munition depot located northeast of the airfield.
 2. To the airfield control tower.
- c. A series of single insulated heavy cables have been laid to a depth of 80 cm below the surface to various points around the airfield. In all cases a trench was dug out and the cable (about four cm in thickness) laid along the bottom. A normal rough domestic brick was then placed across the cable and the earth pushed back into the trench. The route followed by these underground cables is as follows:
 1. Transformer to stand-by generator.
 2. Control tower to eastern point of runway where there is a series of underground pipe lines beneath the runway.
 3. From stand-by generator to the northern perimeter of airfield.
 4. A circuit around the entire runway, about 1.5 meters from its outer edge.
 5. From the northern and southern ends of the runway to two adjoining concrete platforms believed to be sites for future radio installations.

25X1

There are numerous junction boxes located on the surface above this underground system. No permanent lighting system has been built into the concrete runway, nor have any radio installations been constructed.

25X1

5. Aircraft Blast Pens:

No attempt was made at constructing the aircraft blast pens around the fifty dispersal hard stands on the airfield. Near the majority of these hard stands there were piles of prefabricated concrete sections but on 23 April a special break-down type of truck arrived on the airfield and commenced to load the sections onto other trucks. One of the drivers stated that the concrete components were to be dispatched to Gross Doelln airfield.

25X1

25X1

6. Personnel:

- a. At the close of the reporting period there remained a total of about 110 workers from the Deu-Union Brandenburg engaged on the official

S-E-C-R-E-T

25X1

S-E-C-R-E-T

25X1

-3-

cleaning of the airfield and the loading of equipment onto trucks and railway trucks. All workers had been given notice for transfer effective of 1 May.

- b. The only Soviet national remaining on the airfield at the close of the reporting period was a Soviet air force major.
- c. A party of 10 blue-uniformed Volkspolizei men arrived on 18 April to take over the security of the airfield.

7. Miscellaneous:

About 70 of the workers still employed on the airfield have been notified that they are being transferred to Garz airfield where a runway is to be constructed. The remainder of the Bau-Union Brandenburg detachment is to be transferred to Anklam where a nearby airfield is to be rebuilt.

25X1

S-E-C-R-E-T

25X1